

Difficult Shots:

228 - Iron in mature hardwoods pines to south

227 - Iron in mature hardwoods 30" oak 4' to south / Beech & Holly overhead still had leaves

204 - Iron in 30' high young growth pines



Difficult Shots:

212 - Stone 1'NE of 15" Pine in full woods cover

213 - Iron in pine/hardwood cover - post process - did not fix while in woods

217 - Stone down a steep grade next to a small creek branch (see elevations)

220 - Iron 1' SW of 30" Oak in full woods cover