

LAND CORNER RECORD

PIERCE County

T. 19 N, R. 6 East, W.M.

Corner Code No. N - 13

Segregated Surveys:

Name: Southeast Corner of Section 16

Corner No.: n/a

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

Originally set in 1873 by G.L.O. surveyor, Walter B. Hall.

Corner was subsequently restored on 2-28-'68 with a Dept. of Natural Resources concrete monument that replaced the found 24" diameter snag of the original G.L.O. 6" Maple Corner Tree that they found at corner. Monument was set by former DNR employee, Joseph W. Glidden, P.L.S. #9329.

2. Description of Evidence Found:

Above mentioned standard DNR concrete monument with stamped brass cap 1 foot above ground, firmly in the ground.

No evidence was found of the 60" diameter Fir Line Tree stump that Mr. Glidden found south of the corner in 1968.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. 590.02 Page No. 9 Date of work 2-28-'68

590.02 56 4-17-'89

This survey re-referenced concrete monument as shown on reverse side and re-stamped brass cap to read '1989'.

See reverse side for reference points.

89 JUN 21 AM 9:19
RECORDED
BRIAN SOMRITAG
AUDITOR PIERCE CO. WASH

Washington Plane Coordinates: n/a Zone, Y, X
Order Accuracy. Derived From:

Pin Pointed on Photo No. Date Located at

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of Chapter 50, Laws of 1973. Date 6/14/89

Signature Lawrence J. Holt Certificate No. 11977

[SEAL]



AUDITOR'S CERTIFICATE

Filed for record this day of 19 at M. In Book of at page at the request of Washington State Department of Natural Resources.


County Auditor

Form prescribed by Bureau of Surveys and Maps pursuant to the provisions of Section 5 (2), Chapter 50, Laws of 1973.

see Retain

Hazlett
S. Johnson

April 17, 1989



Found std. DNR conc. mon. w/ brass cap set by Glidden's crew on 2/29/68 on pg. 9 of this Field Book - mon. is firmly in place, top of mon. is 1' above ground marked:
T 19 N
16 | 15
21 | 22
R 6 E
~~1968~~

1989
Re-stamped →
today

G.L.O. - 1873 Survey

80.00 ch. - Marked a 6" Maple tree for corner from which:

- 12" Alder - N 71 W - 18 kts. (11.89')
- 10" Alder - S 53 W - 51 kts. (33.66')
- 12" Alder - S 40 E - 22 kts. (14.52')
- 5" Vine Maple - N 13 E - 64 kts. (42.24')

Corner 16/15 21/22 T 19 N R 6 E

Evidence found: The existing DNR conc. mon. w/ brass cap was set on 2/29/68 by Glidden's crew on pg. 9 of this field book. The mon. replaced the 24" diam. snag of the original G.L.O. 6" Maple tree that they found at the corner position. The mon. was found intact today, & new R.P.'s were placed as shown on facing page. Glidden noted in 1968 that he had tied the 2 creeks and the 60" diam. fir line tree stump to the south of this corner called in the G.L.O. notes and they fit this corner position.

AUDITOR'S NOTE

LEGIBILITY FOR RECORDING AND COPYING UNSATISFACTORY IN A PORTION OF THIS INSTRUMENT WHEN RECEIVED.